


## Repair instruction

**Description: C2 C3 C4 (produced after 15 June 2000) Lip seal**


**Part number: 23721**

Look for Service Centers, Point of Sale addresses and other information on: [www.thetford-europe.com](http://www.thetford-europe.com)

<b>Version:</b>	V2
<b>Date:</b>	13/07/2006
<b>Tools required:</b>	

**A**


Remove the sliding Cover.



**B**

Unscrew the 8 screws on the seal cover and, take the seal cover off.

Place new lip seal on the waste tank.  
**Note:** Thinner flange has to face downwards towards the blade.





**C**

Place the lip seal on the waste tank.

Screw the seal cover back onto the waste tank.

Place sliding cover back on its place. Make sure that the two arrows are pointed to each other.



13/07/2006

Description: C2 C3 C4 (produced after 15 June 2000) Lip seal

1